Rev. 0, 6/1/06

GWS 1-10 – Training

Attachment 2, Guidance Matrix for Welder Safety Training

Guidance Matrix for Welder Safety Training

	Training Plan # 2310					Training Plan # 2302	
	Course #	Course #	Course #	Course #	Course #	Course #	Course #
Welding	# 25418	# 9519	# 13088 *	# 15672 **	# 9893 ***	# 9518	# 769
Process	<u>Chemical</u>	Welding Safety	<u>Fire</u>	<u>Fire</u>	<u>Fire</u>	Gas Cylinder	Pressure Safety
	Hazard	(Self-Study)	Extinguisher	Extinguisher:	Extinguisher	<u>Safety</u>	<u>Orientation</u>
	Communication			Designated	Hands-On		
	Introduction			Worker and Fire Watch (Self-	Training		
				Study)			
FCAW no Gas	R	R	R	S	S	N/A	N/A
FCAW +Gas	R	R	R	S	S	R=If bottled gas	R=If manifold
GMAW	R	R	R	S	S	R=If bottled gas	R=If manifold
GTAW	R	R	R	S	S	R=If bottled gas	R=If manifold
GTAW-A	R	R	R	S	S	R=If bottled gas	R=If manifold
OFW	R	R	R	S	S	R=If bottled gas	R=If manifold
PLASMA	R	R	R	S	S	R=If bottled gas	R=If manifold
SAW	R	R	R	S	S	N/A	N/A
SMAW	R	R	R	S	S	N/A	N/A
STUD	R	R	R	S	S	N/A	N/A
TB	R	R	R	S	S	R=If bottled gas	R=If manifold
TF	R	R	R	S	S	N/A	N/A

Note: Courses shown as required are applicable to LANL welders,

- *All Welders should be Fire Extinguisher Trained
- ** This training is required by someone in attendance for all welding operations outside of a Designated Spark and Flame Producing Work area. But the welder himself cannot be the designated Fire Watch. Fire Watch requires a full time person who has completed Fire Extinguisher Designated Worker and Fire Watch Training to be present while welding is conducted and for ½ hour after completion of welding.
- ***Fire watchers shall have fire extinguishing equipment readily available and be trained in its use.